





Oilfield Machine Shop

Plot No. 1, Cape Coast Road, PTC Facility Complex Takoradi, Ghana.

Has completed the qualification for:

BHI-T2 thread recut / repair

In accordance with:

- a) Baker Hughes BHI-T2 Thread Inspection & Rework Procedure all Sizes QP200-006
- b) Thread Root Deep Rolling of Internal and External Threads MPM200
- c) Blunt Start on pin connection threads MPM215
- d) Blunt Start on box connection threads MPM216
- e) Applicable BHI-T2 thread drawings
- f) Shot Peening to Prevent Galling on Surfaces MPM219 (OMS work instruction TQP-26)

Date: 07-January-2014

Jens Hölzel
Supplier Quality Engineer

